

Mine Planning

and its relationship with slope stability & blasting

Small Mines Roadshow 2023

February to March 2023








Presentation covers...

- Mine planning lifecycle
- Consequences of poor planning
- Legislation requirements
- Mine design criteria and information
- Ground or Strata failure (PHMP)
- Slope stability incidents
- Planned assessment results
- Blasting and the mine plan
- Take home messages and questions



Mine planning...

- Financial Model
- Approval Process
- Geology Model 
- Geotechnical Design 
- Environmental considerations
- Stakeholder Liaison
- Plant & Equipment Selection 
- Quarry Closure Plan 
- Review Process



A quarry begins to close the day it opens !

Decisions made during the mine planning and development phase – and even earlier, during the exploration phase – have profound effects on the ultimate closure plan, production outputs and costs, and on the going **safe and efficient** operation of the site.

WE NEED TO GET OUR PLANNING RIGHT !





Consequences of poor mine (pit) planning ? ...



Consequences of poor mine (pit) planning... (some examples)

- **Safety**

- Increased risk to workers and visitors
- Poor access to benches and production areas (roads too steep and narrow)
- Poorly aligned haul roads (switch backs)
- Unstable highwalls (above and below)
- Ground and strata failure (minor and major)
- Increased blasting hazards (flyrock)
- Managing oversize (transport & crushing)
- Can lead to production pressures and shortcuts being taken!



- **Financial**

- Lower annual productivity
- Reduced internal efficiencies (workforce #'s up)
- Inefficient haulage routes
- Double handling (side casting)
- Contamination of products
- Isolation of resource
- Managing oversize (\$\$\$)
- Unable to meet development consent conditions
- Unable to meet market demands (products)
- Increased rehabilitation costs

What does the legislation say?



Survey plans and Mine plans - Work Health and Safety (Mines and Petroleum Sites) Regulation 2022 (Part 6, section 116 – 122)



- A survey plan is required for an underground mine, a coal mine, a petroleum site or a mine determined by the regulator to require one

- A survey plan is also required for a mine, other than an underground mine or coal mine, if the mine operator determines a survey plan is necessary
E.g a risk assessment



Must be prepared by a
registered 'mine surveyor'



Mine Plan – (most in the room will require a ‘mine plan’ not a ‘survey plan’)

- Must be prepared by a competent person
- Must show the following if present at the mine
 - Proposed workings of the mine 
 - Existing workings of the mine, including disused workings
 - Other disused workings that are attached to, or near, the mine
 - The location or estimated location of the boundary of adjacent workings or geological structures
- Plan must be reviewed every 12 months 




Mine Plan

Paper vs Electronic




FORM 20A - EXAMPLE

Example of Mine Plan




Example of Mine Plan

Smaller Mines




- Sequencing
 - Haul roads
 - Parking
 - Boundary
 - Traffic flow
 - Mining criteria
 - Rehab requirements
 - Sign off
- (not all mandatory)

How did you determine your operating parameters and mine design criteria ?



| DOCUMENTATION REVIEW - Control PC1.2 – Mine Design | |
|--------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Objective: <i>The mine design minimises the likelihood of ground or strata failure.</i> | |
| Expected control supports | Assessment outcome |
| <p>CDA - 0201 - PC1.2 - 05 Identified ground stability data is used to produce mine designs and operating parameters.</p> | <p><input type="checkbox"/> Verify that the mine plan and operating parameters have been determined considering the identified ground conditions. <i>Refer to requirements of Clause 123 of WHS (MPS) Regs.</i></p> <p><i>These may include:</i></p> <ul style="list-style-type: none"> ○ Pit boundary. ○ Dump area location and capacity. ○ Smooth wall blasting. ○ Wall angles. ○ Berm widths. ○ Wall heights ○ Dump material composition. ○ Dump height. ○ Dump edge slope. ○ Drainage requirements. |
| Evidence/Observation/Comment: | |

Geotech information - data



*“... and we can save 700 lira
by not taking soil tests...”*

Health and Safety at Quarries Guide



Example of detail in the Guide



Table 2 provides a list of typical issues that are commonly considered during a risk assessment or field investigation regarding actual, or the potential of, ground instability.

| PARAMETER | CONSIDERATIONS |
|---------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Slope type | Active or inactive |
| Slope geometry | Overall slope height, slope angle, bench height, bench slope angle, bench width |
| Engineering Characteristics | Rock or soil, structurally controlled, variable alteration or materials present, material or discontinuity shear strength parameters |
| Proximity of existing infrastructure | Property or services adjacent to both crest and toe of slope, both external and located on site |
| Proximity of workers | Vulnerability, location relative to potential failure |
| Proximity of general public | Proximity of public access, roads, footpaths, walkways and so on |
| Failure mechanism | Planar, wedge, toppling, rotational, liquefaction, toe bulge crest damage |
| Speed of failure | Rapid (flows, rockfall), slow (rotational), very slow (rotational) |
| Water (surface water and groundwater) | Visible signs of seepage or discharge, pore pressures behind high walls, prevention of detrimental effects by effective surface water management, and limiting uncontrolled |
| Recent history of failure | History of instability (type, location and so on), visible signs of active or previous failure (bulging of slope surfaces and so on) |
| Frequency and size of rockfall | The size of the rockfall and ejection or roll out distance (i.e. distance ejected off the batter and potentially down the slope) |

SECTION 3.0 // PLANNING FOR EXCAVATION




Figure 5: 'Soils and very weak rock' guidance







Figure 6: 'Stronger rock' guidance

Other Publications





General Definition of Terms




General Definition of Terms



Slope Design




Overall Pit Angle @ 60 degree face




FOS greater than 2.0

Overall Pit Angle @ 70 degree face



FOS approx. 1.8

Overall Pit Angle @ 85 -90 degree face




Overall Angle = 68 deg

Getting towards an unstable situation

FOS approx. 1.2

Overall Pit Angle @ 85 -90 degree face

Increase bench width from 7.5m – 12m



FOS approx. 1.7

Is Ground or Strata failure a Principal Hazard ?

To determine if ground or strata failure is a principal hazard, consider how an excavation might feasibly fail, and the likely consequences of any such failure. The probability of such a failure happening is not relevant in the context of determining a principal hazard.

The consequences depend on the likely scale of the failure (i.e. the size of the failure and the area affected by it) and whether people are likely to be fatally injured.



PHMP and underpinning risk assessment

Stand alone PHMP with underpinning risk assessment – larger sites

RA & PHMP one in the same document – smaller sites



Woodburn Quarry

**Principal Hazard Plan Ground
or Strata Failure**



| Considerations | Potential hazard | L | C | Risk | Controls used to manage hazard | HoC |
|----------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|----|------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| Geotechnical attributes | <ul style="list-style-type: none"> Failure of highwall due to geological conditions (faults, intrusions, cavities, bedding and jointing) Failure due to no geotechnical expertise involved with bench design Failure to identify and monitor cracks forming on a bench or highwall | L3 | C2 | M8 | Make sure, so far as is reasonably practicable <ul style="list-style-type: none"> Excavation of faces/slope is adequately designed and benched at minimal intervals Accredited and licenced qualified shot firer used for blasting of quarries Monitoring of forming ground cracks on a daily basis whilst quarry is active | 1 4 |
| | | L3 | C3 | M13 | | |
| Pit design & layout | <ul style="list-style-type: none"> Failure of highwall due to excessive face height Failure of highwall due to excessive overall slope angle Failure of highwall due to ineffective bench width Failure due to location and loadings of waste dumps and haul roads | L3 | C2 | M8 | Make sure, so far as is reasonably practicable <ul style="list-style-type: none"> Highwall is benched adequately between 15m - 30 m Total slope angle is less than 27% Benches are constructed to a minimum width and inspected daily for any possible failures Pit layout reduces access to highwall | 1 4 5 |
| | | L3 | C2 | M8 | | |
| | | L3 | C3 | M13 | | |
| | | L4 | C3 | L17 | | |
| Effects of blasting on structure | <ul style="list-style-type: none"> Bench failure due to excessive blast back break Increased fractured ground due to poor blast management practises | L2 | C3 | M9 | Make sure, so far as is reasonably practicable <ul style="list-style-type: none"> Accredited and licenced blasting contractors to be used in quarry Monitoring of fractured ground is carried out to identify any potential hazards | 4 5 |
| Matching machinery | <ul style="list-style-type: none"> Face not adequately scaled due to mismatch of machinery compatibility Working in close proximity to highwall due to incompatible machinery | L3 | C3 | M13 | Make sure, so far as is reasonably practicable <ul style="list-style-type: none"> Machinery is adequate and fit for purpose Good blasting practices to ensure good access to materials for machinery Face height does not exceed the reach of the machinery to be used | 4 5 |
| | | L3 | C2 | M8 | | |

Schedule 1 Principal hazard management plans—additional matters to be considered

(Sch 19 model WHS Regs)

Part 1 Mines

1 Ground or strata failure

- (1) The following matters must be considered in developing the control measures to manage the risks of ground or strata failure—
- (a) the local geological structure,
 - (b) the local hydrogeological environment, including surface and ground water,
 - (c) the means by which water may enter the mine, and the procedures for removing water from the mine and the effect that those procedures have on rock stability over time,
 - (d) the geotechnical characteristics of the rocks and soil, including the effects of time, oxidation and water on rock support and stability,
 - (e) the timing of installation of ground and strata support for the mine, taking into account the geotechnical conditions and behaviour of the rocks and soil,
 - (f) the collection, analysis and interpretation of relevant geotechnical data, including the monitoring of openings and excavations,
 - (g) any natural or induced seismic activity,
 - (h) the equipment and procedures used to record, interpret and analyse data from the monitoring of seismic activity,
 - (i) the location and loadings from existing or proposed mine infrastructure such as waste dumps, tailings storage, haul roads and mine facilities,
 - (j) any previously excavated or abandoned workings,
 - (k) the proposed and existing mining operations, including the nature and number of excavations, the number and size of permanent or temporary voids or openings, backfilling of m
 - (l) the proposed blasting activities (including the design, control and monitoring of each blast),
 - (m) the design, layout, operation, construction and maintenance of any dump, stockpile or emplacement area at the mine, including any open cut dumps or stockpiles,
 - (n) the filling requirements for mined areas and the material to be used as fill,
 - (o) the stability of any slopes,
 - (p) the size and geometry of the mine's openings,
 - (q) the use of appropriate equipment and procedures for scaling,
 - (r) the design, installation and quality of rock support and reinforcement,
 - (s) the need to monitor areas at or around the mine where control measures are in place for the principal hazard of ground or strata failure,

WHS (MPS)Reg 2022 Schedule 1

Ready made prompt list

Subject Matter Experts – (when) ?

As a guide:

- > Simple operations (e.g. shallow depth, soft material with faces less than 3.5 m, or competent rock with faces less than 15 m). A competent person should determine if the face design is safe, adequate benching is in place, or arrange for a geotechnical assessment. Assessments should be in writing, dated and signed with a review period established.
- > Complex operations (e.g. individual faces exceeding 15 m, overall excavation depth exceeding 30 m, fractured rock, disturbed geological structure) will require a geotechnical assessment by a competent person.


A geotechnical assessment should be completed where:

- > the height of any individual face is more than 15 m
- > in the case of 'soils and highly weathered or friable rock' where the height of any part of an excavation is more than 3.5 m and the overall slope angle is steeper than 2 horizontal to 1 vertical (27° to the horizontal) (see Figure 4)
- > the bottom of the excavation is more than 30 metres below any surrounding land within 30 metres of the edge of the excavation (i.e. the excavation is more than 30 metres deep, allowing for any nearby higher ground) (see Figure 5).

- > Complex operations (e.g. individual faces exceeding 15 m, overall excavation depth exceeding 30 m, fractured rock, disturbed geological structure) will require a geotechnical assessment by a competent person.



External reports (initial and on going)

| Bench 3 | Description / Comment | | | | |
|-------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------|--------------|---------|
| Drainage | Acceptable | | | | |
| Stability | Large undercut unstable wedge at northern end of bench. Could impact existing haul ramp. Batter angles over-steepened or undercut in parts. Loose blocks and wedges perched precariously on batter. | | | | |
| Deformation | Minor in parts | | | | |
| Crest Cracking | Yes, extensive in weathered rock sections | | | | |
| Modes of Failure | Rock wedge slide and flexural toppling along jointing and bedding. Block topple and fall from loose rocks on batter and over steepened or undercut batters. | | | | |
| Batter Angle | 70-90° | Bench Width | 1-20 m | Bench Height | 10-25 m |
| General Condition | <ul style="list-style-type: none"> Bench widths in north are narrow, particularly in southern section (< 1.5 m). Bench heights are too high in northern and eastern sections. Bench in north is segmented due to slope failures (refer Bench 1 above). Bench widths are narrow in southern section (< 1.5 m). This poses a safety risk as there are limited escape routes in an emergency. Batter slope angles are over steepened in places. | | | | |
| Photo | <p>Unstable large wedge directly above main haul ramp with bulging in rock column near toe.</p>  <p>Bench 3 - west</p> <p>Unstable wedges above haul ramp</p> <p>Rock bulging</p> | | | | |
| Unmitigated Risk | High | | | | |
| Risk Mitigation | <ul style="list-style-type: none"> Implement a no stop zone and maintain bund at toe of slope. Reduce batter angle in over-steepened sections. Increase bench width in southern section. Buffer and toe restraint bunds are needed between road and batter slope to reduce risk of rock impacting vehicles and personnel. Buttress with fill rock undercuts and bulging to provide wedge toe support. Planning of future works adjacent to the unstable wedges is to include methodologies for safe wedge removal, e.g., excavation towards the wedges and then safe wedge removal from or above (rather than from below). | | | | |




Pictorial view of risk assessment




Domains:


| | | | |
|---------|----------------------------------|------------------------------------------------------------------------------------------------------------------------------------|-------------------|
| Area 1: | Main Waste Dump | Should be monitored routinely for stability | Low Risk |
| Area 2: | Western Haul Road Infrastructure | | Low Risk |
| Area 3: | Northern Upper Pit - Weathered | Haul road bench widths to be enforced. | Low Risk |
| Area 4: | Northern Lower Pit - Unweathered | Only work quarry faces if required and use SWP's. Check scale as required. Be aware of intersection of haul road with puggy fault. | Low Risk |
| Area 5: | Quarry Floor | | |
| Area 6: | Lower Eastern Pit - Unweathered | Only approach faces if required. Be aware of large slabby blocks. Check scale as reqd. | Low/Moderate Risk |
| Area 7: | Upper Eastern Pit - Weathered | Control drainage and check scale as reqd. | Low Risk |
| Area 8: | Puggy Fault | Routinely record movement on structure | Low/Moderate Risk |



Bedding and face orientation




Side elevation – bedding dipping into the face




Side elevation – bedding dipping out of the face


Bedding perpendicular to the face



Plan view of Quarry face



Bedding at acute angle



Bedding at acute angle to face orientation

Beware of wedge failures

Plan view of Quarry face

In Pit (local) geological structures



- Bedding running at an acute angle to face
- Major fault cuts through entire deposit

2022 – severe weather



SAFETY BULLETIN

DATE: 14 MARCH 2022

Impacts of severe weather on slope stability

This safety bulletin provides safety advice for the NSW mining industry.

Background

Large parts of New South Wales have experienced significant rainfall over the past several days.

Severe weather events can disrupt mining operations as well as impact safe access and egress from mines. This safety bulletin serves as a reminder to people conducting a business or undertaking as a mine operator or contractor, to consider the risks posed by significant rainfall impacting slope stability of excavations, quarry benches, dumps and other structures.

Hazards

Prolonged rainfall can saturate soils, cause pooling on surfaces, lubrication of faults and cause erosion of roads and ramps. This can impact the safety of workers and safe access and egress to and from mine working areas.

Recommendations

Mine operators should monitor conditions and identify areas where the potential exists for slopes to fail. Areas which have potential to fail must be managed to ensure that workers are not impacted if a slope failure occurs. Monitor highwalls and benches for cracking, fretting and any other signs of movement. Ensure that drains are functioning correctly so that flood water cannot pool on the surface of highwalls, benches and dumps. Keep workers and equipment away from areas where stability has been compromised by recent rainfall.

NOTE: Please ensure all relevant people in your organisation receive a copy of this safety bulletin and are informed of its content and recommendations. This safety bulletin should be processed in a systematic manner through the mine's information and communication process. It should also be placed in the mine's common area, such as your notice board where appropriate.

January 2023



- Currently being investigated by external geotech (likely to be geology contact)
- Establish failure mode
- Revise mine plan
- Implement action plan


Doesn't have to be hard rock ! (circa 2004)




Can be under the water!

(circa 2001)

- Change of mining method
- Undercut the working area
- No systematic approach
- No edge protection



Catch bund design ?



Working near faces !



Stockpile extraction at small site !



Can happen to excavators ?

- Fit for purpose equipment
- Correct and agreed setup
- Workers trained in slope stability awareness
- Scaling practices in place
- Inspection systems in place





Figure 38. Rock trap design

Separating people and parking locations!



Separate people from the ground or strata hazard

- Indicators of potential failure are identified and people are subsequently protected from areas of risk.



Safety Alert 2020



NSW
Resources
Regulator

SAFETY BULLETIN

DATE: FEBRUARY 2020

Failure of highwalls, low walls and dumps

This safety bulletin provides safety advice for the NSW mining industry.

Issue

Several incidents have been reported recently where people and equipment have been exposed to significant health and safety risks as a result of highwalls, low walls and dumps failing.

Circumstances

These types of failures can occur at any time in open cut mines and quarries.

Incidents reported to the NSW Resources Regulator show the frequency of this type of incident increases significantly during and post wet weather events.

Figure 1 Recent highwall failure February 2020



SAFETY BULLETIN

NSW
Resources
Regulator



Figure 2 Recent highwall failure January 2020



Recommendations



Safety Bulletin - recommendations

1. **Installation and maintenance of water drainage** to prevent pooling of water
2. **Pumps are installed and operational** where required, prior to wet weather events
3. Thorough **inspections are completed by supervisors** prior to and during mining operations (results are recorded and communicated)
4. **Increase frequency of inspections** of highwalls and dumps during wet weather
5. **Workers to monitor conditions** in work areas
6. **Scaling of walls** to be completed during excavation
6. **Avoid working near, or parking vehicles** and equipment under, or on edge of highwalls during and post weather events
7. **Geotechnical assessments** are completed by qualified people and regular reports are provided to workers
8. Where possible **consider use of drones** to inspect wall conditions
9. **Access is available above and below** walls and dumps to allow inspections to be conducted
10. **Access is restricted to high risk areas** (e.g. dykes, faulted areas) until hazards are identified and controlled

Dump construction




Figure 39. Example of tip slope stability design (limit equilibrium)




Figure 40. Example dump construction method for mixed material (mattressing)




Figure 41. Example dump construction method for competent material




Figure 43. Approaching tip point windrow






Figure 45. Dump on level ground with a slight uphill gradient



Dump to design

- Factors which affect dump stability are identified, dumps are correctly constructed, and dumps are inspected and monitored for compliance.

Instability or movement in dumps and stockpiles can cause serious harm. To minimise this risk, actively manage dumps and stockpile, and have robust procedures in place.

This section describes:

- > common risks from dumps, stockpiles dumps and tipping materials and ways to control them
- > procedures for inspecting tip heads and tip condition.

Incidents can occur for various reasons when dumping. These reasons are unsafe dump head conditions, unsafe dumping practices or a combination of the two.

Some unsafe dump point conditions include:

- > **No windrow or restraint, or an inadequate windrow or restraint.** This makes the edge location difficult to judge, offers inadequate restraint to keep a vehicle from going over the edge.
- > **A windrow that is too narrow at the base.** This allows the heavy loading of the truck to get so close to the edge of the dump that the edge material may not be strong enough to support the weight.
- > **An edge of a dump that has been weakened** because the dump has been loaded out at the toe and over steepened. Edge material may not be able to support the truck weight and its own weight. A portion of the windrow may have fallen away, reducing the windrow's capability to provide restraint.
- > **An edge of a dump that has been undercut.** Overhanging conditions can be created especially when the dump material is frozen, or has sat for an extended period.
- > **Cracks, settlement, or a slide near the edge of the dump.** The edge may be unstable and may not support the additional truck weight.
- > **A soft area near the edge of the dump** may cause tyres to sink in and the truck to tip over as it attempts to dump.
- > **A dump that runs downgrade to the windrow.** Gives drivers less control while backing and can soften the dump area from poor drainage.
- > **A dump that's placed on a soft or weak foundation.** As the dump gets larger, the slope may become unstable due to the foundation giving way underneath.
- > **Inadequate lighting for night operations,** or poor visibility during inclement weather. Makes driver judgements, and detection of unsafe conditions, more difficult.
- > **Inadequate clearance** between equipment and overhead power lines. Two particular concerns are that truck trays are raised at dump points, and as dumps get larger the clearance may become reduced.
- > **Congestion around the dump head** where dump trucks or other mobile machinery congregate and crowd the dump head due to operational delays or unplanned events.

Inspections – (pit, face, dumps stockpiles)



| Inspection (by who) | Frequency |
|--------------------------------|------------------------|
| Extraction team | Daily (prior to work) |
| Supervisor | Daily |
| Quarry Manager | Routinely |
| Internal professionals | As required |
| External Subject Matter Expert | As required (annually) |

Week start date: 27/6/22
Week end date: 27/6/22

Daily Quarry Site Inspection

Tick when checked // Cross when action needed

| | 27 | 28 | 29 | 30 | 1 | 2 |
|---------------------------------------|-----|----|----|----|----|----|
| Load & Haul Operation | | | | | | |
| Haul road condition | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Bunding | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Access any restrictions | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Drainage | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Flooding | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Bench Face Operation | | | | | | |
| Work face condition | * ↓ | No | No | ✓ | ✓ | ✓ |
| Work face not undercut | * ↓ | No | No | ✓ | ✓ | ✓ |
| Bench face for faults / hazards | * ↓ | No | No | ✓ | ✓ | ✓ |
| Work floor condition | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Drainage | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Flooding | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Sales Area | | | | | | |
| Work floor condition | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Stockpiles not undercut | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Stockpile signage | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Bunding | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Drainage | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Work Shop | | | | | | |
| Neat & clean | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Free of hazards | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Lighting | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Tools locked away from previous shift | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Fuel bowser locked | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Entering Site & Security | | | | | | |
| Front gate locked | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Work shed locked | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Office buildings locked | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Initial | JB | JB | JB | JB | JB | JB |

Comments:

Working face operator daily checklist

Monday Date: 27/6/22

| | Mon | Tue | Wed | Thu | Fri | Sat |
|---------------------------------------------------|-----|-----|-----|-----|-----|-----|
| Check working face condition is acceptable | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Check working face is not undercut | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Check face for faults and fall hazards | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Ensure bunding is the correct height and in place | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Ensure work floor is level and clear of hazards | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Create rock trap between face and work pad | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Build pad to suitable height for loading | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Identify any seepage as potential weak area | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Operator sign off | GC | GC | GC | GC | GC | GC |

Comments:

27/6 WEDGE FAILURE SOUTH EAST CORNER OF PIT NEAR HAUL ROAD.

Slope stability inspections can extend to ongoing monitoring...

- visual inspection
- surface extensometers and crack monitoring
- Manual survey
- Real time GPS stations with prisms
- radar
- micro-seismic monitoring
- monitoring of groundwater pressure.
- Use of a drone



Planned assessment results

Resources Regulator
Department of Regional NSW




Consolidated report

Ground or strata failure – slope stability – small mines

February 2022 – August 2022

Fact sheet – Ground or strata failure – small mines



NSW Resources Regulator

FACT SHEET

Assessment program - Ground or strata failure – slope stability
Small mines

January 2022



The principal mining hazard of ground or strata failure can occur through various mechanisms at surface mining operations. This can therefore potentially place workers at risk if not controlled effectively. The management of slope stability is a key mechanism within this process and should be assessed both individually and cumulatively with other hazards.

The Resources Regulator is commencing a program of planned inspections and targeted assessments at small mines focussing on the critical controls associated with slope stability. The assessments will be focussed on the following criteria:



Mine design

- Ground stability risks are assessed and controlled within the mine design and mine operating parameters.

Water management

- Controls for risks to ground or strata from water damage are implemented.

FACT SHEET
Ground or Strata Failure – Slope Stability
Small Mines

NSW Resources Regulator



Dump to design

- Factors which affect dump stability are identified, dumps are correctly constructed, and dumps are inspected and monitored for compliance.



Excavate to design

- Walls are excavated to design and cleared of loose material.



Separate people from the ground or strata hazard

- Indicators of potential failure are identified and people are subsequently protected from areas of risk.

FACT SHEET
Ground or Strata Failure – Slope Stability
Small Mines

NSW Resources Regulator



Operator protection

- Plant design provides a barrier for falling objects and also prevents workers from being crushed in a rollover event.

Considerations

Mine operators should consider the above criteria as a minimum, ensuring such information is included within their principal hazard management plans and associated documentation. Following investigations into strata failure incidents within the mining industry, it was evident that non-compliance to these key control measures contributed to incident outcomes, which caused both severe and fatal injuries to workers. When identifying and implementing control measures, mines are also reminded to follow the hierarchy of controls to ensure health and safety risks are minimised so far as is reasonably practicable.

Other relevant safety alerts and bulletins published by the NSW Resources Regulator:

| DATE PUBLISHED | REFERENCE | TITLE |
|----------------|-----------|----------------------------------------------------------------------------|
| February 2020 | SB20-01 | Failure of highwalls |
| August 2019 | SB19-09 | Lack of bunding on accessible edges |
| December 2018 | SA18-13 | Dangerous incident involving excavator on edge of highwall |
| July 2018 | SA18-09 | Drill rig breaches highwall windrow |
| July 2018 | SB18-11 | Windrow management and demarcation |
| March 2017 | SB17-03 | Rocks breach catch bund |
| January 2017 | SB17-01 | Industry reports more truck rollover incidents |
| November 2014 | IR14-06 | Track mounted excavator tip over |

© State of New South Wales through Regional NSW 2022. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website. Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (December 2021) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication. DOC21/108805

Ground or Strata failure consolidated report findings...

Throughout the inspection program, there were several examples where sites could demonstrate a good application in controlling the principal hazard of ground or strata failure – slope stability.

Improvement areas were also identified and discussed with the sites during the assessments for managing their ground or strata hazards.

- **Areas for improvement:**
- Documentation **not relevant, site specific** or up to date
- Excavations **not meeting design criteria** or mine plan
- Lack of understanding to **inspect blast hole logs** and anomalies
- **Water management practices** not documented and regularly inspected



Ground or Strata failure consolidated report findings...continued !

- **Equipment setup up procedures** adjacent to geological structures not documented
- **Inspections not routinely** completed
- **Absence of awareness training** for workers and supervisors
- Disconnect between **blast management plan and mine plan** (reliance on contractors)
- **Non reporting** of ground and strata failures to the Regulator




Drilling and Blasting practices



| FIELD VERIFICATION - Control PC1.4 – Drilling and blasting practices | | | | | | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|-------------------------------|---|---|---|--|
| Objective: Achieve stable wall conditions. | | | | | | |
| Expected control supports | Rating | Assessment outcome / comments | | | | |
| <p>CIA - 0201 - PC1.4 - 02; CIA - 0201 - PC1.4 - 03; CIA - 0201 - PC1.4 - 06; CIA - 0201 - PC1.4 - 08</p> <p>Confirm that quarry manager/supervisor can explain the key features of the drill plan.</p> <p>Key features could include:</p> <ul style="list-style-type: none"> Pre-splitting or trim shot detail. Formation of benches Drill hole <ol style="list-style-type: none"> Correct location Correct angle Correct depth Maintaining hole logs | <table border="1"> <tr> <td>4</td> <td>3</td> </tr> <tr> <td>2</td> <td>1</td> </tr> </table> | 4 | 3 | 2 | 1 | |
| 4 | 3 | | | | | |
| 2 | 1 | | | | | |
| <p>CIA - 0201 - PC1.4 - 07</p> <p>Confirm that information relevant to the blast design is recorded in the hole logs.</p> <p>Relevant information may include:</p> <ul style="list-style-type: none"> Deviation from planned hole location or angle. Holes drilled short of planned length. Broken ground or voids encountered | <table border="1"> <tr> <td>4</td> <td>3</td> </tr> <tr> <td>2</td> <td>1</td> </tr> </table> | 4 | 3 | 2 | 1 | |
| 4 | 3 | | | | | |
| 2 | 1 | | | | | |
| <p>CIA - 0201 - PC1.4 - 09</p> <p>Confirm that the blast holes have been checked prior to loading for anomalies such as water in the holes, collapsed or blocked holes.</p> <p>Relevant information may include:</p> <ul style="list-style-type: none"> Check loading records from most recent blast | <table border="1"> <tr> <td>4</td> <td>3</td> </tr> <tr> <td>2</td> <td>1</td> </tr> </table> | 4 | 3 | 2 | 1 | |
| 4 | 3 | | | | | |
| 2 | 1 | | | | | |

Figure 8. Overall assessment findings ratings for critical control – PC1.4 Drilling & blasting practices (total 107 findings)

PC1.4 - Drilling & blasting practices





- Documented & implemented
- Implemented but not documented
- Documented but not implemented
- Not documented and not implemented
- Not applicable/Not assessed


Disconnect between **blast management plan (design)** and **mine plan** (reliance on contractors) ?

| Criteria group | Critical control | Control support number | Criteria Text | Enforcement action | | |
|----------------|-------------------------------|------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|----------------------|-------------|
| | | | | Concern (s23) | Contravention (s191) | Grand Total |
| PC1.4 | Drilling & blasting practices | 02 | CIA - 0201 - PC1.4 - 03; CIA - 0201 - PC1.4 - 06; CIA - 0201 - PC1.4 - 08 Confirm that quarry manager/supervisor can explain the key features of the drill plan. | 2 | 4 | 6 |
| | | 07 | Confirm that information relevant to the blast design is recorded in the hole logs. | 4 | 5 | 9 |
| | | 09 | Confirm that the blast holes have been checked prior to loading for anomalies such as water in the holes, collapsed or blocked holes. | 6 | 6 | 12 |

Lack of understanding to inspect blast hole logs and anomalies ? (Laser profile)



Face survey showing scan area and hole markers



...and Bore Tracking



Drillers Scorecard

Location: Teven
 Title: North Teven Rd Teven
 Filename: BTQ-2202_Argellite_Level1
 Comment: BTQ-2202_Argellite_Level1.spf
 Danny Adams

ORICA

| Row ID | Hole ID | Drill Depth | 3m Down (Error mm) | | | Mid-Blasthole (Error mm) | | | Grade-Blasthole (Error mm) | | | Accuracy % |
|--------|---------|-------------|--------------------|---------|------|--------------------------|---------|------|----------------------------|---------|------|------------|
| | | | <100 | 100-200 | >200 | <400 | 400-700 | >700 | <400 | 400-700 | >700 | |
| A | A1 | 10.6 | | X | | X | | | | | | |
| A | A2 | 10.6 | | X | | X | | | | | | 45 |
| A | A3 | 10.8 | X | | | X | | | X | | | 75 |
| A | A4 | 11.0 | | X | | X | | | X | | | 80 |
| A | A5 | 10.8 | X | | | X | | | X | | | 75 |
| A | A6 | 11.5 | X | | | X | | X | | | | 100 |
| A | A7 | 11.5 | | X | | X | | X | | | | 100 |
| A | A8 | 11.5 | X | | | X | | | X | | | 75 |
| A | A9 | 11.4 | X | | | X | | X | | | | 100 |
| A | A10 | 11.5 | | X | | X | | | X | | | 80 |
| A | A11 | 11.0 | | X | | | X | | | | X | 30 |
| | | | | X | | | X | | | | X | 30 |
| E | E15 | 13.5 | X | | | X | | | | X | | 80 |
| E | E16 | 13.4 | X | | | X | | | | X | | 80 |

Drill logs

- Correct starting location
- Correct depth
- Correct inclination
- Any geological anomalies
- Any water intersection
- Correct loading amounts

Talk to the driller and shotfirer

80

Driller's Log

Mine: Boral Culcairn
Location: Culcairn
Surveyor: Ernest Martyn
Filename: CC_Bench1_102
Date: 7/03/2022

Fullbore
QUARRY SERVICES

Ground Condition: S: Soft H: Hard B: Broken W: Wet C: Clay V: Void

| Hole ID | Diameter mm | Design Angle | Design Depth | Measured Depth | Comments |
|---------|-------------|--------------|--------------|----------------|---------------|
| A1 | 89 | 30 | 20.6 | 20.6 | C5M-HD |
| A2 | 89 | 30 | 20.6 | 20.6 | C5M-HD |
| A3 | 89 | 30 | 20.5 | 20.4 | C4.5M-5.5M-HD |
| A4 | 89 | 30 | 20.4 | 20.4 | C4.5M-5.5M-HD |
| A5 | 89 | 30 | 20 | 20.1 | C1.5M-5.5M-HD |
| A6 | 89 | 25 | 18.8 | 18.7 | S-3M-HD |
| A7 | 89 | 25 | 18.8 | 18.9 | S-2M-HD |
| A8 | 89 | 20 | 18.1 | 18.2 | S-2.5M-HD |
| A9 | 89 | 22.5 | 18.2 | 18.2 | S-2M-HD |
| B1 | 89 | 20 | 19 | 19.1 | S/C-6.5-HD |
| B2 | 89 | 20 | 19 | 19 | S/C-6.5-HD |
| B3 | 89 | 20 | 19.1 | 19 | S/C-6M-HD |
| B4 | 89 | 20 | 19 | 19 | S/C-6M-HD |
| B5 | 89 | 20 | 18.7 | 18.8 | S/C-5.8-HD |
| B6 | 89 | 20 | 18.4 | 18.4 | S/C-5.9-HD |
| B7 | 89 | 20 | 18.2 | 18.3 | S/C-4.5M-HD |
| B8 | 89 | 17.5 | 17.9 | 18 | S/C-4M-HD |
| B9 | 89 | 17.5 | 17.8 | 18 | S/C-3.5M-HD |
| C1 | 89 | 15 | 18.5 | 18.6 | S/C-5M-HD |
| C2 | 89 | 15 | 18.6 | 18.6 | S/C-5M-HD |
| C3 | 89 | 15 | 18.5 | 18.6 | S/C-5M-HD |
| C4 | 89 | 15 | 18.3 | 18.4 | S/C-4M-HD |
| C5 | 89 | 15 | 18.2 | 18.2 | S/C-4M-HD |
| C6 | 89 | 12.5 | 17.8 | 18 | S/C-3.5-HD |
| C7 | 89 | 10 | 17.5 | 17.5 | S/C-3.5-HD |
| C8 | 89 | 10 | 17.4 | 17.4 | S/C-3M-HD |
| C9 | 89 | 12.5 | 17.5 | 17.4 | S/C-3M-HD |
| D1 | 89 | 10 | 18.2 | 18.1 | S/C-7M-HD |
| D2 | 89 | 10 | 18.2 | 18.3 | S/C-6.5-HD |
| D3 | 89 | 10 | 18.2 | 18.3 | S/C-5M-HD |
| D4 | 89 | 10 | 18.1 | 18 | S/C-6M-HD |
| D5 | 89 | 10 | 18 | 18 | S/C-6M-HD |
| D6 | 89 | 10 | 17.9 | 18 | S/C-6M-HD |
| D7 | 89 | 10 | 17.7 | 18 | S/C-6M-HD |
| D8 | 89 | 10 | 17.7 | 17.8 | S/C-6M-HD |
| D9 | 89 | 10 | 17.5 | 17.6 | S/C-7M-HD |
| D10 | 89 | 10 | 17.4 | 17.3 | S/C-8M-HD |
| E1 | 89 | 10 | 18.2 | 18 | S/C-4M-HD |
| E2 | 89 | 10 | 18.2 | 18 | S/C-7M-HD |
| E3 | 89 | 10 | 18.2 | 18.1 | S/C-5M-HD |
| E4 | 89 | 10 | 18.2 | 18 | S/C-5.5M-HD |

RD Blocked

Bench Access – think ahead !






FIELD VERIFICATION - Control PC1.6 – Water Management

Objective: *Water is diverted or removed to prevent ground or strata failure.*

| Expected control supports | Rating | Assessment outcome / comments | | | | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|-------------------------------|---|---|---|--|
| <p>Select a sample of nominated water management controls identified in the SMS related to ground or strata failure.</p> <p>Controls may include:</p> <ul style="list-style-type: none"> • Ground water bores and associated pumping and level monitoring. • Sub horizontal drainage holes in walls. • Run off diversion and drainage. • Pit pumping arrangements for removing pooled water. | | | | | | |
| <p>CIA - 0201 - PC1.6 - 02</p> <p>Confirm the nominated water management controls are implemented to the specified design.</p> | <table border="1"> <tr> <td>4</td> <td>3</td> </tr> <tr> <td>2</td> <td>1</td> </tr> </table> | 4 | 3 | 2 | 1 | |
| 4 | 3 | | | | | |
| 2 | 1 | | | | | |
| <p>CIA - 0201 - PC1.6 - 03</p> <p>Confirm the nominated inspection and monitoring arrangements are in place.</p> <p>These may include:</p> <ul style="list-style-type: none"> • Rain levels. • Ground water levels – piezometers. • Maintenance and inspection of water management controls. • Water pooling at dump bases • Drains in place free from silt. | <table border="1"> <tr> <td>4</td> <td>3</td> </tr> <tr> <td>2</td> <td>1</td> </tr> </table> | 4 | 3 | 2 | 1 | |
| 4 | 3 | | | | | |
| 2 | 1 | | | | | |



Check sheet



MINE PLANNING - SELF ASSESSMENT

(this document does not guarantee compliance and should be used as a guidance tool only)


| | | Yes/No |
|--------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|
| Approval Conditions: | <ol style="list-style-type: none"> 1. Do you have a current copy of your development consent & conditions? 2. Do you regularly review compliance with these conditions? 3. Does your team understand your consent condition requirements? 4. Have you considered drafting a development consent conditions map? | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> |
| Geology: | <ol style="list-style-type: none"> 1. Do you have an up-to-date geological map including reserves? 2. Does your map distinguish between various quarry products? 3. Is your drilling data catalogued and stored for future use? 4. Is geological assessment an integral component of your on going mine planning? | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> |
| Geotechnical Design Criteria: | <ol style="list-style-type: none"> 1. Have you considered geotechnical criteria in your pit design? 2. Have you identified areas where additional geotechnical controls are needed? 3. Have you considered drafting a risk rated geotechnical plan of your site? 4. Do you have design criteria and inspection checklists to ensure compliance? | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> |
| Haul Roads : | <ol style="list-style-type: none"> 1. Do you have a documented haul road design guideline? 2. Have you considered and documented haul road locations (short & long term)? 3. Do you have scheduled haul road maintenance and inspection systems? 4. Do you have a traffic management plan for your site? | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> |
| Blast & Environment : | <ol style="list-style-type: none"> 1. Are your environmental conditions understood by your team? 2. Have you considered the preparation of an environmental conditions map? 3. Do your blasting procedures include environmental conditions and an exclusion zone? 4. Are your inspection, monitoring & recording systems for environmental matters documented? | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> |
| Rehabilitation & Closure: | <ol style="list-style-type: none"> 1. Do you have a progressive "live" quarry rehabilitation plan in place? 2. Have you been progressively completing rehabilitation in accordance with the plan? 3. Do your inspection and monitoring programs include your completed rehabilitation? 4. Are you planning financially to honour your agreed rehabilitation obligations? | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> |
| Stakeholders : | <ol style="list-style-type: none"> 1. Have you imbedded agreed consultation processes in each of your programs ? 2. Are you being proactive in your stakeholder dealings? 3. Are you scheduling and managing internal and external reviews in a systematic manner? 4. Is there a continuous improvement requirement in each of your programs? | <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> |

"All mine planning programs include stakeholder engagement - remember to manage it proactively"



Take home messages...

- Ensure your mine plan is current and displayed
- Discuss with your supervisors and team
- Understand your mine design criteria
- Revisit your PHMP for ground or strata failure
- Review your DA consent conditions and display
- Discuss with your blasting contractor your mine plan requirements
- Provide your workers with slope stability awareness training
- **Make sure your inspections are happening !**





Any questions?