

Weekly incident summary

Week ending 2 June 2023

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.


At a glance

High level summary of emerging trends and our recommendations to operators.



Type	Number
Reportable incident total	42
Summarised incident total	3

Summarised incidents

Incident type	Summary	Comments to industry
Dangerous Incident IncNot0044783 Open cut coal mine Roads or other vehicle operating areas	A dozer operator was preparing coal on a shared workbench. The operator was aware of the edge of the bench as the dozer trammed forward. The operator felt a track slump. The operator then tried to reverse but the whole side gave way, resulting in the dozer rolling onto its roof. The bench was about 4 metres high, and conditions were reported as dusty.	When dozers are working parallel to edges, the risk of the dozer inadvertently breaching the edge must be considered, and controls put in place such as windrows. When determining lighting requirements, secondary tasks in the area must be considered. The impact of lighting and shadowing on edges near work areas should be factored into work planning and lighting placement.



Weekly incident summary week ending 2 June 2023

Incident type	Summary	Comments to industry
<p>Dangerous Incident IncNot0044771 Underground coal mine</p>	<p>A worker was driving a load haul dump (LHD) that overheated on the main travelling road. The operator removed the header tank cap and was sprayed with hot coolant. The worker was taken to the surface and then to hospital where he was transferred to a specialist burns unit. The worker was treated for superficial burns to the arm, chest and thigh.</p> 	<p>Workers must not remove caps on coolant systems without first relieving the stored pressures. If there is any residual pressure at all in the cooling system, it may cause the coolant to vigorously boil when the system is open to atmospheric pressure.</p> <p>Mine operators should inspect all coolant systems to ensure warnings are in place and a means is available to dissipate the stored pressure to protect workers from exposure to hot coolant. Each radiator filler and radiator cap should be arranged or interlocked so that coolant pressure is safely released prior to the cap being able to be removed.</p>
<p>Dangerous Incident IncNot0044768 Underground coal mine Fire or explosion</p> 	<p>A continuous miner was cutting in a place change panel. A frictional ignition occurred as the miner sumped into the left hand side of the face and intersected a borehole. The ignition started at the cutter head with a loud pop. Orange flames then travelled over the miner to the rear of the miner body. The flames were extinguished after about 30 seconds. Workers at the crib room felt a pressure change and their ears popped. No workers were injured.</p>	<p>An investigation has commenced and further information may be released in future.</p>

Other Resources Regulator publications

[Safety Bulletin SB23-05 Contraband in underground coal mines](#)

Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

Publication	Issue/topic
	National (other, non-fatal)

Weekly incident summary week ending 2 June 2023

Publication	Issue/topic
Resources Safety & Health Queensland	<p>While investigating the cause of a mine dozer shutting down, a coal mine worker opened a diesel particulate matter filter compartment and observed that the filters were beginning to ignite. The worker extinguished the fire. Smoke from the incident entered an inbye panel, workers in the panel subsequently retreated to a place of safety. It has been confirmed that the scrubber water feed isolation valve was in the off position and the safety circuit flow controller was nearly fully wound out. This has rendered the scrubber low water and it shut down to be ineffective.</p> <p>Details</p>

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2023. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (June 2023) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

Document control	
CM9 reference	RDOC23/115576
Mine safety reference	ISR23-21
Date published	9 June 2023
Authorised by	Deputy Chief Inspector Office of the Chief Inspector