

# Weekly incident summary

## Week ending 27 October 2023

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

### At a glance

High level summary of emerging trends and our recommendations to operators.

Type	Number
Reportable incident total	61
Summarised incident total	5



### Summarised incidents

Incident type	Summary	Comments to industry
Dangerous incident IncNot0045641 Underground coal mine	While in the process of recovering a compressed air pipe range, the range was isolated and de-energised before work commenced. However, a 13 metre section of pipe that had a closed gate valve was still energised. When the worker started to remove the quick release clamp his left forearm was hit with compressed air.	<p>Effective isolation and energy dissipation practices are critical risk controls when working with high pressure air systems.</p> <p>Where stored pressure can remain in a circuit (such as check valves and gate valves), appropriate methods must be available to safely dissipate pressure.</p> <p>Mines' risk assessments on pressure systems must identify and provide effective controls for areas of trapped pressure.</p> <p><b>Refer to:</b> <a href="#">Investigation information release (IIR22-01) Two mine workers injured during pipe installation work</a></p>
Dangerous incident IncNot0045653 Underground metals mine Ground or strata failure	<p>While securing mesh with a multibolter the temporary roof support (TRS) was pushed to the roof and then released to preposition the last sheet of mesh. When the TRS was lowered, it caused a parting layer of tops to fall onto the walkway of the multibolter.</p> <p>There were 2 workers on the multibolter. No-one was injured.</p>	<p>Underground mines should review the adequacy of their strata monitoring arrangements and associated trigger action response plans (TARPs), to ensure that workers are not exposed to unacceptable risks associated with strata failure.</p> <p><b>Refer to:</b> <a href="#">NSW code of practice - Strata control in underground coal mines</a></p>

## Weekly incident summary week ending 27 October 2023

Incident type	Summary	Comments to industry
	<p>The piece of stone was about 750 mm wide, 1000 mm long and 180 mm thick.</p>	
<p data-bbox="124 465 379 663">           Dangerous incident            IncNot0045655            Open cut coal mine            Roads or other vehicle operating areas         </p> 	<p data-bbox="416 465 943 651">           A rear dump truck reversed into a tip area to tip its load. The truck backed up to and through a dump windrow with both sets of dual tyres, causing the truck to become stuck on the dump edge with its belly on the ground and duals over the edge.         </p> 	<p data-bbox="975 465 1445 562">           Windrow design, construction and maintenance is a critical factor in dump safety. Mines operators should:         </p> <ul data-bbox="995 577 1461 909" style="list-style-type: none"> <li>• design and construct windrows adequately to be a control for the hazard at the operation, paying specific attention to set-back distances, heights and material used</li> <li>• regularly inspect and maintain windrows through open cut examiner inspections and operator inspections.</li> </ul> <p data-bbox="975 920 1382 1016"> <b>Refer to:</b> <a href="#">Safety Bulletin SB18-11 Windrow management and demarcation</a> </p>
<p data-bbox="124 1048 384 1205">           Dangerous incident            IncNot0045656            Underground metals mine         </p>	<p data-bbox="416 1048 948 1330">           A truck tyre was being transported underground on the forks of an integrated tool carrier (IT). While driving down the decline, the tyre came off the forks and rolled down the decline striking the rear of a popping rig that was tramping down the decline. The tyre continued rolling before stopping 500 metres from where it dislodged from the forks.         </p> 	<p data-bbox="975 1048 1465 1234">           Workers should ensure that loads are adequately secured to prevent unplanned movement. Using slings, support cradles or suitable jigs appropriately rated for the load, should be considered.         </p> <p data-bbox="975 1249 1445 1346">           Documented procedures providing step-by-step instructions for the task should be provided to workers.         </p> <p data-bbox="975 1361 1414 1424">           Supervisors should ensure that the approved procedures are followed.         </p>
<p data-bbox="124 1720 368 1895">           Dangerous incident            IncNot0045666            Open cut coal mine            Fire or explosion         </p>	<p data-bbox="416 1720 887 1816">           An excavator caused an unintended initiation of explosives while filling an excavator bucket with overburden.         </p> <p data-bbox="416 1832 919 1957">           Fly rock from the explosion hit the windscreen of the excavator resulting in laminated glass inside the operator's cabin. No rock penetrated the glass.         </p> <p data-bbox="416 1973 935 2036">           An adjacent haul truck sustained damage to the side mirror and some debris on the         </p>	<p data-bbox="975 1720 1461 2036">           Sites must maintain effective explosives management systems. These systems should include safe work procedures and signed off checklists that minimise the potential for misfires and/or unaccounted explosives devices. There must be a process in place to ensure any misfires are identified, logged and communicated to workers.         </p>

# Weekly incident summary week ending 27 October 2023

Incident type	Summary	Comments to industry
	<p>walkway. A nearby dozer also had fly rock material impact the machine. The haul truck and dozer were about 5-10 metres from the bucket when the incident occurred. There were no injuries suffered by any of the operators.</p> 	

## Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

Publication	Issue/topic
	<p><b>International (fatal)</b></p>
<p><b>MSHA</b></p>	<p>On October 2, 2023, a miner died after he was pinned between a shuttle car and a coal rib. This is the 35th fatality reported in 2023, and the 10th classified as powered haulage.</p> <p>Best practices:</p> <ul style="list-style-type: none"> <li>• When working around mobile equipment, communicate your presence and intended movements to equipment operators. Wait for acknowledgement before moving.</li> <li>• Avoid red zone areas where equipment operators cannot readily see you.</li> <li>• Increase the visibility of miners by using reflective clothing and/or strobe light devices.</li> </ul> <p><u><a href="#">Details</a></u></p>
<p><b>MSHA</b></p>	<p>On September 17, 2023, contractor driller helper died while driving a service truck to transport a rod handler on the bed. The service truck left the road, overturned, and the</p>

## Weekly incident summary week ending 27 October 2023

Publication	Issue/topic
	<p>driver was ejected. The passenger, who was wearing his seat belt, was injured, treated and released from the hospital.</p> <p>Best practices:</p> <ul style="list-style-type: none"> <li>• Wear seat belts when operating mobile equipment.</li> <li>• Conduct pre-operational inspections and correct any safety defects before operating mobile equipment.</li> <li>• Maintain control of equipment.</li> <li>• Operate mobile equipment at speeds consistent with the conditions of roadways, tracks, grades, clearance, visibility, curves, and traffic.</li> </ul> <p><a href="#">Details</a></p>
	<p><b>National (other, non-fatal)</b></p>
<p><b>Resources Safety &amp; Health Queensland</b></p>	<p>Resources Safety and Health Queensland is urging coal mines operators to be more hands on when it comes to preventing one of the mining industry's most common serious accidents. Since 2021, 55 serious accidents involving fingers have been reported at Queensland coal mines; of these 28 happened this year (2023). A quarter of the reported serious accidents involve considerable risk activities associated with lifting, slinging and towing. Additionally, approximately another 20 high potential incidents involving fingers have been reported.</p> <p><a href="#">Details</a></p>

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2023. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing ([Month YYYY]) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

Document control	
CM9 reference	DOC23/361835
Mine safety reference	ISR23-xx
Date published	3 November 2023
Authorised by	Director of Regulatory Operations Office of the Chief Inspector