

Weekly incident summary

Week ending 10 May 2024


This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

At a glance



High level summary of emerging trends and our recommendations to operators.

| Type | Number |
|---------------------------|--------|
| Reportable incident total | 38 |
| Summarised incident total | 3 |


Summarised incidents

| Incident type | Summary | Comments to industry |
|---|--|--|
| Dangerous incident IncNot0046876 Open cut coal mine Fire or explosion  | An excavator operator noticed excess oil on top of the stairs and the engine compartment of the excavator. Fitters attended to degrease the oil spill, which occurred from a failed hose. The fitters put degreaser on the roof of the engine compartment to clean up the excess oil. When they went into the engine room, they saw degreaser dripping through the roof. The degreaser fell onto a hot exhaust manifold and started a fire. The fitters exited the engine room, passed the fire and activated the fire suppression system. | Where products such as cleaners and degreasers are used near hot engine components, the ignition point should be assessed and compared with surface temperatures to manage the risk of fires. When selecting products, higher ignition point products should be used. AS 5062:2022 Fire prevention and protection for mobile and transportable equipment was published in November 2022. Mine operators should review this document and update their systems and site procedures. |

Weekly incident summary week ending 10 May 2024

| Incident type | Summary | Comments to industry |
|---|---|--|
|  <p data-bbox="124 1451 355 1744">Dangerous incident IncNot0046873 Underground coal mine Ground or strata failure</p>  | <p data-bbox="392 1451 967 1895">A breakaway was being cut in an intersection with a continuous miner. The miner commenced cutting the breakaway and in doing so, a rib mesh sheet was caught on the miner apron. The mesh was damaged in between the rib bolts. The miner was flitted outbye to continue cutting the turn and a vent tube was required to be recovered. As the vent tube was being recovered, the rib slumped between the 2 sets of rib bolts and damaged the mesh, hitting a worker on the left foot and lacerating his toes.</p> | <p data-bbox="999 1451 1469 1720">Mine operators should have a procedure in place to assess the risk of slumping, following damage to rib mesh, particularly when the mesh has been torn and exposes the rib. Workers must remain aware of strata conditions.</p> |

Weekly incident summary week ending 10 May 2024

| Incident type | Summary | Comments to industry |
|---|---|--|
| <p data-bbox="113 226 384 259">Dangerous incident</p> <p data-bbox="113 271 384 304">IncNot0046869</p> <p data-bbox="113 315 384 349">Underground metals mine</p> <p data-bbox="113 360 384 394">Roads or other vehicle operating areas</p> |  <p data-bbox="392 226 967 969">A haul truck collided head-on with the wall of a decline when the steering function failed because of fluid loss from a damaged hydraulic hose.</p> <p data-bbox="392 981 967 1417">The operator was uninjured.</p> | <p data-bbox="975 226 1497 745">Safety critical systems such as braking and steering systems should be inspected, maintained and tested in accordance with the manufacturer's recommendations.</p> <p data-bbox="975 757 1497 1417">Mine operators must develop and adhere to strict inspection and maintenance standards and practices to prevent loss of fluid due to loose fittings or damaged hoses. Operators should review their maintenance procedures to ensure commissioning checks are carried out by competent people before plant is returned to service as fit-for-purpose.</p> |

Weekly incident summary week ending 10 May 2024

| Incident type | Summary | Comments to industry |
|---|---|----------------------|
|  |  | |

Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

| Publication | Issue/topic |
|--------------------|--|
| | <p>International (fatal)</p> |
| <p>MSHA</p> | <p>On December 14, 2023, at 2:40pm, Jay Swaffar, a 56-year-old BEST Electric shop assistant with no mining experience, died when an all-terrain telehandler, being used to pull electrical cable, tipped over and hit him.</p> <p>The accident occurred because BEST Electric did not:</p> <ul style="list-style-type: none"> • ensure proper task training was provided to the miner operating the telehandler, • ensure the telehandler operator-maintained control of the equipment, and • ensure the telehandler was not being used beyond the design capacity intended by the manufacturer where such use may create a hazard to persons. <p>Details</p> |
| <p>MSHA</p> | <p>On February 6, 2023, at 3:45pm, Javier Regalado-Cano, a 61-year-old haul truck driver with over a year of mining experience, was fatally injured when he suffered an electric shock. While Regalado-Cano was operating a haul truck, he raised the bed of the haul truck into the energised overhead 13,800-volt phase-to-phase power lines. Regalado exited the haul truck and extinguished a fire on the haul truck's left rear dual tires. Regalado suffered an electric shock when he made contact with the energised haul truck while re-entering it.</p> <p>The accident occurred because the mine operator did not:</p> <ul style="list-style-type: none"> • install warning devices for the power lines, and |

Weekly incident summary week ending 10 May 2024

| Publication | Issue/topic |
|------------------------------------|--|
| | <ul style="list-style-type: none"> de-energise or take other precautionary measures when mobile equipment was operating near energised power lines. <p>Details</p> |
| National (other, non-fatal) | |
| WorkSafe Victoria | <p>An employee was working as an underground drill operator. He was injured when he used a hardened steel hammer to strike a hardened steel drill shank. The employee was trying to separate jammed drill consumables by striking the shank. He was hurt when the hammer shattered on impact. Steel fragments hit one of the employee's legs, penetrating 4 cm. He required surgery to remove the fragments.</p> <p>Using hardened steel tools on hardened steel can cause the steel to shatter or splinter. Steel fragments can fly off at high speed and cause injuries or death. To control risks:</p> <ul style="list-style-type: none"> identify and assess hazards use alternative non-hardened steel tools if possible regularly inspect tools for damage and fatigue ensure employees wear appropriate PPE. <p>Details</p> |

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2024. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (May 2024) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

| Document control | |
|-----------------------|---|
| CM9 reference | DOC24/104515 |
| Mine safety reference | ISR24-19 |
| Date published | 17 May 2024 |
| Authorised by | Director Technical Operations, Mine Safety Office of the Chief Inspector |