

Safety Alert

Date: September 2024

Fire occurs on longwall face in underground coal mine

This safety alert provides safety advice for the NSW mining industry.

Issue

A fire occurred in front of the face side of the tailgate cutter drum of an operational shearer in a NSW underground coal mine on 26 August 2024.

Circumstances

Two operators were remotely operating a longwall from an operating centre on the surface of a mine. The shearer had cut out the tailgate snake and was hauling towards the maingate leading up to the incident.

The shearer failed to clear the tailgate snake area completely when haulage stopped after the anti-collision haulage function tripped. At the same time, the Armoured Face Conveyor (AFC) panline advanced on the bank push, which forced the tailgate drum into the face. The drum continued to rotate, which generated frictional heat. The cutting horizon consisted of a metre of sandstone/siltstone from the floor with a metre of coal above that.

After several minutes, flames erupted in the area immediately in front of the tailgate drum. This was captured on the system's continuous video display and the surface operator stopped the drum rotation. The flames were extinguished by the shearer drum sprays before the worker on the face, who was about 40 metres away, had time to intervene. Having been alerted to the fire by the surface operating centre, the worker on the face proceeded to the shearer and made the area safe by dousing it with water.

Investigation

The mine has determined there were deficiencies in the programming of the automation process that allowed the AFC panline to advance while the shearer was not clear of the advancing panline. This forced the face side of the tailgate drum into the coal face, which consequently generated sufficient frictional heat to ignite the coal that was immediately in front of the drum.

All frictional ignition controls were found to be compliant after the incident, with the shearer drum cutter picks and sprays in excellent condition. Air quantity across the longwall face was 40 cubic metres/second and the tailgate was liberally stone dusted.

Safety Alert SA24-03

Methane was not believed to have been a factor in this event, with no monitoring detecting above 0.2% at any time before, during, or after the incident.

Figure 1: The tailgate drum



Recommendations

Mine operators should:

- review their automated cutting processes with specific emphasis on the suitability of controls within the software to prevent automated commands that may result in creating unsafe conditions
- communicate this alert to workers who are engaged in overseeing remote mining operations to highlight the challenges that exist with regard to identifying unsatisfactory operating conditions in a timely manner before a dangerous incident occurs underground.

Note: Please ensure all relevant people in your organisation receive a copy of this safety alert and are informed of its content and recommendations. This safety alert should be processed in a systematic manner through the mine's information and communication process. It should also be placed on the mine's common area, such as your notice board where appropriate.

Safety Alert SA24-03

Visit our [website](#) to:

- find more safety alerts and bulletins
- use our searchable safety database

© State of New South Wales through the Department of Primary Industries and Regional Development 2024. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute the Department of Primary Industries and Regional Development as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (September) and may not be accurate, current or complete. The State of New South Wales (including Department of Primary Industries and Regional Development), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

Document control	
CM10 reference	RDOC24/170095
Mine safety reference	SA24-03
Date published	13 September 2024
Authorised by	Chief Inspector Office of the Chief Inspector