

WEEKLY INCIDENT SUMMARY

Week ending Friday 21 August 2020

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

At a glance

High level summary of incidents and our comments to operators.

TYPE	NUMBER
Reportable incident total	37
Summarised incident total	2

Summarised incidents

INCIDENT TYPE	SUMMARY	COMMENTS TO INDUSTRY
Dangerous incident IncNot0038029 Underground metals mine	<p>During shaft-lining operations, a winch cable snapped, resulting in a shotcrete hose-reeler moving about two metres and hitting the back of the shaft-lining rig.</p> <p>Up to 700 kilograms was suspended from the shaft-lining rig at the time. The lining rig weighed about 12 tonnes and was on the ground near the shaft opening. The cable reeler weighed about two tonnes and was behind the lining rig.</p>	<p>Winch ropes should be regularly inspected during all tasks. Triggers for rope replacement should be determined according to the task, the rating of the ropes and the risk associated with rope failure.</p> <p>Mines must identify all risks associated with rope failure and implement controls to protect workers in the event of a failure, such as safe standing zones and remote operation.</p>



Plant that has the potential to move under strain should be secured in position where possible.

Death
IncNot0038051
Underground
coal mine

A worker was found unresponsive in a load haul dump machine (LHD) on the main travel road at an underground coal mine. Attempts to revive the worker were unsuccessful.
The LHD was running at the time the worker was found.

This incident is under investigation and the cause of death is unknown at the time of publication.

Refer to [incident at Springvale Mine](#).

Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

PUBLICATION	ISSUE/TOPIC
-------------	-------------

International (fatal)

MSHA

Mine fatality

On 18 August 2020, a 21-year-old labourer, who was employed at a mine, entered a cone crusher to remove a blockage in the material chute. While he was inside the crusher cone an amount of material flowed from the chute, engulfing his legs and lower torso. He was extricated by emergency services and flown to hospital. He died later the next day. An investigation into the incident is continuing.

[Details](#)

National (other, non-fatal)

DNRME (Qld)

Managing gas on open cut coal mines – Mines safety bulletin no.186

Coal mine workers at open cut sites are often not aware that flammable and toxic gases may be present and pose a significant risk during normal mining activities at open cut operations.

[Details](#)

**Queensland
Mines
Inspectorate
(Coal)**

Methane ignited by friction generated during rib bolting – Safety Alert No.375

During the installation of a steel rib bolt, frictional contact between the rotating steel bolt and a steel rib mesh strand generated enough heat to ignite methane that was present behind the plate at the installation point.

[Details](#)

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2020. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (August 2020) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL

CM9 reference

DOC20/688996

Mine safety reference

ISR20-34

Date published

31 August 2020

Approved by

Chief Inspector
Office of the Chief Inspector