

# Mine safety performance overview

## **+** Fatal injuries **↑↑ 2** INCREASE OF 2 IN 2018-19 FROM 0 IN 2017-18

### Metalliferous mine

A contract worker suffered spinal injuries from a fall from an elevated work platform. The scissor lift's front and left side guard rails had been removed to move it under a steel structure. While on the scissor lift platform using its control unit, the worker lost balance and fell off the platform from a height of about one metre. The worker experienced a series of complications secondary to surgery and passed away six weeks after the incident.

See [Investigation Information Release IIR18-14](#) for more information.

### Coal mine

A tyre maintenance worker was fatally injured when a large earthmoving tyre fell from a tyre handler at the mine's heavy vehicle wash bay. The tyre maintenance worker and another worker had removed the tyre from a water cart at a service bay with the tyre handler. The tyre handler was then used to take the tyre to the nearby wash bay for cleaning. At some point during the cleaning process, the tyre fell onto the tyre maintenance worker. Other workers responded to the scene and initiated the mine's emergency response procedures.


See [investigation report and animation](#) for more information.

## **+** Serious injuries **↑↑ 93** INCREASE OF 11 IN 2018-19 FROM 82 IN 2017-18

## **+** Fatal and serious injuries

### Fatal and serious injuries snapshot

MECHANISM
Being hit by moving object (41%)
Falls, trips and slips of a person (29%)




NATURE OF INJURY
Fracture (52%)
Wounds, lacerations, amputations and internal organ damage (24%)

\*Represents 70% of the total

\*Represents 67% of the total

\*Represents 76% of the total

### Fatal and serious injuries by sector (one person = 2 serious injuries)



## **+** LTIs LOST TIME INJURIES

**↑↑ 295** INCREASE OF 35 IN 2018-19 FROM 260 IN 2017-18


## **+** TRIs TOTAL RECORDABLE INJURIES

**↓↓ 959** DECREASE OF 16 IN 2018-19 FROM 975 IN 2017-18

# Mine safety performance overview


## LTIFR

Five year average lost time injury frequency rate



## TRIFR


Five year average total recordable injury frequency rate




## Incidents **2,031**

INCREASE OF 17 IN 2018-19 FROM 2,014 IN 2017-18


Incident notifications by sector and operation type



Incident notification annual frequency rate




## Incident notification profile 2018-19




# Mine safety performance overview

**Notices issued** **↑ 1,774** INCREASE OF 17 IN 2018-19 FROM 2,014 IN 2017-18

## Notices issued by sector




## Notices issued by type



**Hours worked** **↑ 69.1m** INCREASE OF 4.3m IN 2018-19 FROM 64.8m IN 2017-18

## Total hours worked in 2018-19



## For more information

This overview was first published in August 2020 with data current at May 2020.

To read the full **Mine Safety Performance Report for 2018 - 2019**, and other safety publications, visit our website: [resourcesregulator.nsw.gov.au](https://resourcesregulator.nsw.gov.au)

© State of New South Wales through Regional NSW 2020. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website. Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (August 2020) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication. DOC20/625400

